

FIG. 1
(PRIOR ART)

Slice group	1					FoV read	300		[mm]
Slices	2					FoV phase	100.0		[%]
Dist. factor	20					Slice thickness	5.0		[mm]
Position	Isocenter					TR	300		[ms]
Orientation	Transversal					TE	15		[ms]
Phase enc. dir.	A>>P					Averages	1		
Phase oversampling	0					Concatenations	1		
						Filter	None		
						Coil elements	BC		

Slices 1 2 10

FIG. 2
(PRIOR ART)

Slice group	1					FoV read	300		[mm]
Slices	2					FoV phase	100.0		[%]
Dist. factor	20					Slice thickness	5.0		[mm]
Position	Isocenter					TR	300		[ms]
Orientation	Transversal					TE	15		[ms]
Phase enc. dir.	A>>P					Averages	1		
Phase oversampling	0					Concatenations	1		
						Filter	None		
						Coil elements	BC		

TR 300 56 5000

FIG. 3
(PRIOR ART)

Slice group	1	FoV read	300	[mm]
Slices	12	FoV phase	100.0	[%]
Dist. factor	20	Slice thickness	5.0	[mm]
Position	Isocenter	TR	3000	[ms]
Orientation	Transversal	TE	15	[ms]
Phase enc. dir.	A>>P	Averages	1	
Phase oversampling	0	Concatenations	1	
		Filter	None	
		Coil elements	BC	

Slices 1 12 108

FIG. 4
(PRIOR ART)

Slice group	1	FoV read	300	[mm]
Slices	12	FoV phase	100.0	[%]
Dist. factor	20	Slice thickness	5.0	[mm]
Position	Isocenter	TR	332	[ms]
Orientation	Transversal	TE	15	[ms]
Phase enc. dir.	A>>P	Averages	1	
Phase oversampling	0	Concatenations	1	
		Filter	None	
		Coil elements	BC	

TR 332 5000

FIG. 5

Slice group	1		FoV read	300	[mm]
Slices	2		FoV phase	100.0	[%]
Dist. factor	20	[%]	Slice thickness	5.0	[mm]
Position	Isocenter		TR	300	[ms]
Orientation	Transversal		TE	15	[ms]
Phase enc. dir.	A>>P		Averages	1	
Phase oversampling	0	[%]	Concatenations	1	
			Filter	None	
			Coil elements	BC	

Slices 2
1 10 128

Confirm Parameter Changes

Your last change

Slices: 2 ...> 12




has adapted the following parameters:

TR: 300 ...> 332 [ms]

OK

Undo

FIG. 6




A.S. 10/31/00
P.K. 10/31/00
T.H. 10/31/00

A.S. 10/31/00
P.K. 10/31/00
T.H. 10/31/00
A.S. 10/31/00
P.K. 10/31/00
T.H. 10/31/00

A.S. 10/31/00
P.K. 10/31/00
T.H. 10/31/00

FIG. 8




A.S. 10131100
 P.K. 10131100
 T.H. 10131100

A.S. 10131100
 P.K. 10131100
 T.H. 10131100

A.S. 10131100
 P.K. 10131100
 T.H. 10131100

A.S. 10131100
 P.K. 10131100
 T.H. 10131100

FIG. 9

A.S. 10/31/00
P.K. 10/31/00
T.U. 10/31/00

A.S. 10/31/00
P.K. 10/31/00
T.U. 10/31/00

A.S. 10/31/00
P.K. 10/31/00
T.U. 10/31/00

add life lines, please